



MICROCHIP

PIC18F2220/2320/4220/4320

PIC18F2220/2320/4220/4320 Rev. B3 Silicon Errata

The PIC18F2220/2320/4220/4320 Rev. B3 parts you have received conform functionally to the Device Data Sheet (DS39599F), except for the anomalies described below.

All the problems listed here will be addressed in future revisions of the PIC18F2220/2320/4220/4320 silicon.

The following silicon errata apply only to PIC18F2220/2320/4220/4320 devices with these Device/Revision IDs:

Part Number	Device ID	Revision ID
PIC18F2220	0000 0101 100	0 0100
PIC18F2320	0000 0101 000	0 0100
PIC18F4220	0000 0101 101	0 0100
PIC18F4320	0000 0101 001	0 0100

The Device IDs (DEVID1 and DEVID2) are located at addresses 3FFFFEh:3FFFFh in the device's configuration space. They are shown in binary in the format "DEVID2 DEVID1".

1. Module: Internal Oscillator Block

If the INTRC clock source was not started at POR (any VDD) and VDD is greater than 4.5V, the INTRC clock source may not start or may require a long delay when starting. The INTRC may not restart when VDD is lowered below 4.5V.

Features that depend on the operation of the INTRC clock source may be affected. These include the INTOSC output when exiting from Sleep mode, the Watchdog Timer (WDT) if enabled by firmware using the WDTCON register, Two-Speed Start-ups during Reset or wake-up from Sleep and the Fail-Safe Clock Monitor (FSCM) when exiting Sleep mode.

The INTOSC frequency may rise very high (for example, 9.5 MHz). The WDT and the FSCM may simply not function. Two-Speed Start-ups may not occur, but execution will start once the primary clock source becomes ready.

Work around

Several work arounds may be used.

1. Enable the WDT in Configuration register, CONFIG2H and place a CLRWDT instruction somewhere in the main loop.
2. Configure the internal oscillator block as the primary clock source using Configuration Register 1H.
3. Any technique that starts the INTRC at Reset and does not disable it may be used.
4. Ensure that VDD is below 4.5V when starting the INTRC clock source.

There may be other work arounds.

Date Codes that pertain to this issue:

All engineering and production devices.

2. Module: Core (DAW Instruction)

The DAW instruction may improperly clear the Carry bit (STATUS<0>) when executed.

Work around

Test the Carry bit state before executing the DAW instruction. If the Carry bit is set, increment the next higher byte to be added, using an instruction such as INCF SZ (this instruction does not affect any Status flags and will not overflow a BCD nibble). After the DAW instruction has been executed, process the Carry bit normally (see Example 1).

EXAMPLE 1: PROCESSING THE CARRY BIT DURING BCD ADDITIONS

```

MOVLW 0x80      ; .80 (BCD)
ADDLW 0x80      ; .80 (BCD)

BTFSC STATUS, C ; test C
INCF SZ byte2   ; inc next higher LSB
DAW
BTFSC STATUS, C ; test C
INCF SZ byte2   ; inc next higher LSB

This is repeated for each DAW instruction.

```

Date Codes that pertain to this issue:

All engineering and production devices.

PIC18F2220/2320/4220/4320

3. Module: Internal Oscillator Block

At high temperature (above 85°C) or low VDD (below 2.5V), the IOFS bit (OSCCON<2>) may not become set when the internal oscillator block is selected as the system clock source for any frequency above 31 kHz (OSCCON<6:4> ≠ 000). The INTOSC output will stabilize at 8 MHz; however, the IOFS bit may not become set.

Work around

If time critical code is to be executed, it should be delayed by 1 ms following the operation that enables the 8 MHz INTOSC output from the internal oscillator block.

Date Codes that pertain to this issue:

All engineering and production devices.

4. Module: INTOSC

Incrementing or decrementing the value in the OSCTUNE register may not have the expected effect of shifting the INTRC or INTOSC output frequencies. The OSCTUNE values beyond which this happens may vary with temperatures above 70°C.

Work around

None

Date Codes that pertain to this issue:

All engineering and production devices.

5. Module: MSSP (All I²C™ and SPI Modes)

The Buffer Full flag bit (BF) of the SSPSTAT register (SSPSTAT<0>) may be inadvertently cleared, even when the SSPBUF register has not been read. This will occur only when the following two conditions occur simultaneously:

- The four Least Significant bits of the BSR register are equal to 0Fh (BSR<3:0> = 1111) and
- Any instruction that contains C9h in its 8 Least Significant bits (i.e., register file addresses, literal data, address offsets, etc.) is executed.

Work around

Identified work arounds will involve setting the contents of BSR<3:0> to some value other than 0Fh.

In addition to those proposed below, other solutions may exist.

1. When developing or modifying code, keep these guidelines in mind:
 - Assign 12-bit addresses to all variables. This allows the assembler to know when Access Banking can be used.
 - Do not set the BSR to point to Bank 15 (BSR = 0Fh).
 - Allow the assembler to manipulate the Access bit present in most instructions. Accessing the SFRs in Bank 15 will be done through the Access Bank. Continue to use the BSR to select all GPR Banks.
2. If accessing a part of Bank 15 is required and the use of Access Banking is not possible, consider using indirect addressing.
3. If pointing the BSR to Bank 15 is unavoidable, review the absolute file listing. Verify that no instructions contain C9h in the 8 Least Significant bits while the BSR points to Bank 15 (BSR = 0Fh).

Date Codes that pertain to this issue:

All engineering and production devices.

6. Module: MSSP (SPI, Slave Mode)

In its current implementation, the \overline{SS} (Slave Select) control signal generated by an external master processor may not be successfully recognized by the PIC[®] microcontroller operating in Slave Select mode (SSPM3:SSPM0 = 0100). In particular, it has been observed that faster transitions (those with shorter fall times) are more likely to be missed than slower transitions.

Work around

Insert a series resistor between the source of the \overline{SS} signal and the corresponding \overline{SS} input line of the microcontroller. The value of the resistor is dependent on both the application system's characteristics and process variations between microcontrollers. Experimentation and thorough testing is encouraged.

This is a recommended solution; others may exist.

Date Codes that pertain to this issue:

All engineering and production devices.

7. Module: Data EEPROM

When writing to the data EEPROM, the contents of the data EEPROM memory may not be written as expected.

Work around

Either of two work arounds can be used:

1. Before beginning any writes to the data EEPROM, enable the LVD (any voltage) and wait for the internal voltage reference to become stable. LVD interrupt requests may be ignored. Once the LVD voltage reference is stable, perform all EEPROM writes normally. When writes have been completed, the LVD may be disabled.
2. Configure the BOR as enabled (any voltage). Select a threshold below VDD to allow normal operation. If VDD is below the BOR threshold, the device will be held in BOR Reset.

Date Codes that pertain to this issue:

All engineering and production devices.

8. Module: Oscillator Configurations (OSCTUNE Register)

The INTRC and INTOSC clock sources are both adjusted using the OSCTUNE register and may not be adjusted separately. Peripherals that use the INTRC clock source (WDT and FSCM) also are affected.

Work around

None.

Date Codes that pertain to this issue:

All engineering and production devices.

9. Module: Oscillator Configurations (OSCTUNE 2 Register)

This revision of silicon does not have the OSCTUNE 2 register. Address F9Bh is not implemented.

Work around

If the INTRC frequency is to be adjusted, modify the contents of the OSCTUNE register.

Date Codes that pertain to this issue:

All engineering and production devices.

10. Module: Oscillator Configurations (INTOSC Clock Source)

The INTOSC clock source requires more start-up time than what is stated in the data sheet. The IOFS bit (OSCCON<2>) will indicate the INTOSC has settled in approximately 4 ms.

Work around

None.

Date Codes that pertain to this issue:

All engineering and production devices.

PIC18F2220/2320/4220/4320

REVISION HISTORY

Rev A Document (04/2004)

First revision of this document, silicon issues 1 (Internal Oscillator Block), 2 (Core – DAW Instruction), 3 (Internal Oscillator Block), 4 (INTOSC), 5 (MSSP – All I^2C and SPI Modes), 6 (MSSP – SPI, Slave Mode), 7 (Data EEPROM) and data sheet clarification issues 1 (RE3 Pin), 2 (Timer1 Oscillator), 3 (Enhanced PWM Module Block Diagram), 4 (Enabling SPI I/O), 5 (DC Characteristics), 6 (DC Characteristics) and 7 (LVD Characteristics).

Rev B Document (02/2005)

Added Data Sheet Clarification issue 8 (PIC18F4220/4320 Pinout I/O Descriptions).

Rev C Document (03/2005)

Added Data Sheet Clarification issue 9 (Pinout I/O Descriptions).

Rev D Document (10/2007)

Removed all Data Sheet Clarifications. Added silicon issues 8-10 (Oscillator Configurations).

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

Trademarks

The Microchip name and logo, the Microchip logo, Accuron, dsPIC, KEELOQ, KEELOQ logo, microID, MPLAB, PIC, PICmicro, PICSTART, PRO MATE, rPIC and SmartShunt are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.


AmpLab, FilterLab, Linear Active Thermistor, Migratable Memory, MXDEV, MXLAB, SEEVAL, SmartSensor and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, Application Maestro, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, dsSPEAK, ECAN, ECONOMONITOR, FanSense, FlexROM, fuzzyLAB, In-Circuit Serial Programming, ICSP, ICEPIC, Mindi, MiWi, MPASM, MPLAB Certified logo, MPLIB, MPLINK, PICkit, PICDEM, PICDEM.net, PICLAB, PICtail, PowerCal, PowerInfo, PowerMate, PowerTool, REAL ICE, rLAB, Select Mode, Smart Serial, SmartTel, Total Endurance, UNI/O, WiperLock and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2007, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

 Printed on recycled paper.

**QUALITY MANAGEMENT SYSTEM
CERTIFIED BY DNV
== ISO/TS 16949:2002 ==**

Microchip received ISO/TS-16949:2002 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC® MCUs and dsPIC® DSCs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.



WORLDWIDE SALES AND SERVICE

AMERICAS

Corporate Office
2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200
Fax: 480-792-7277
Technical Support:
<http://support.microchip.com>
Web Address:
www.microchip.com

Atlanta

Duluth, GA
Tel: 678-957-9614
Fax: 678-957-1455

Boston

Westborough, MA
Tel: 774-760-0087
Fax: 774-760-0088

Chicago

Itasca, IL
Tel: 630-285-0071
Fax: 630-285-0075

Dallas

Addison, TX
Tel: 972-818-7423
Fax: 972-818-2924

Detroit

Farmington Hills, MI
Tel: 248-538-2250
Fax: 248-538-2260

Kokomo

Kokomo, IN
Tel: 765-864-8360
Fax: 765-864-8387

Los Angeles

Mission Viejo, CA
Tel: 949-462-9523
Fax: 949-462-9608

Santa Clara

Santa Clara, CA
Tel: 408-961-6444
Fax: 408-961-6445

Toronto

Mississauga, Ontario,
Canada
Tel: 905-673-0699
Fax: 905-673-6509

ASIA/PACIFIC

Asia Pacific Office
Suites 3707-14, 37th Floor
Tower 6, The Gateway
Harbour City, Kowloon
Hong Kong
Tel: 852-2401-1200
Fax: 852-2401-3431

Australia - Sydney
Tel: 61-2-9868-6733
Fax: 61-2-9868-6755

China - Beijing
Tel: 86-10-8528-2100
Fax: 86-10-8528-2104

China - Chengdu
Tel: 86-28-8665-5511
Fax: 86-28-8665-7889

China - Fuzhou
Tel: 86-591-8750-3506
Fax: 86-591-8750-3521

China - Hong Kong SAR
Tel: 852-2401-1200
Fax: 852-2401-3431

China - Nanjing
Tel: 86-25-8473-2460
Fax: 86-25-8473-2470

China - Qingdao
Tel: 86-532-8502-7355
Fax: 86-532-8502-7205

China - Shanghai
Tel: 86-21-5407-5533
Fax: 86-21-5407-5066

China - Shenyang
Tel: 86-24-2334-2829
Fax: 86-24-2334-2393

China - Shenzhen
Tel: 86-755-8203-2660
Fax: 86-755-8203-1760

China - Shunde
Tel: 86-757-2839-5507
Fax: 86-757-2839-5571

China - Wuhan
Tel: 86-27-5980-5300
Fax: 86-27-5980-5118

China - Xian
Tel: 86-29-8833-7252
Fax: 86-29-8833-7256

ASIA/PACIFIC

India - Bangalore
Tel: 91-80-4182-8400
Fax: 91-80-4182-8422

India - New Delhi
Tel: 91-11-4160-8631
Fax: 91-11-4160-8632

India - Pune
Tel: 91-20-2566-1512
Fax: 91-20-2566-1513

Japan - Yokohama
Tel: 81-45-471- 6166
Fax: 81-45-471-6122

Korea - Daegu
Tel: 82-53-744-4301
Fax: 82-53-744-4302

Korea - Seoul
Tel: 82-2-554-7200
Fax: 82-2-558-5932 or
82-2-558-5934

Malaysia - Kuala Lumpur
Tel: 60-3-6201-9857
Fax: 60-3-6201-9859

Malaysia - Penang
Tel: 60-4-227-8870
Fax: 60-4-227-4068

Philippines - Manila
Tel: 63-2-634-9065
Fax: 63-2-634-9069

Singapore
Tel: 65-6334-8870
Fax: 65-6334-8850

Taiwan - Hsin Chu
Tel: 886-3-572-9526
Fax: 886-3-572-6459

Taiwan - Kaohsiung
Tel: 886-7-536-4818
Fax: 886-7-536-4803

Taiwan - Taipei
Tel: 886-2-2500-6610
Fax: 886-2-2508-0102

Thailand - Bangkok
Tel: 66-2-694-1351
Fax: 66-2-694-1350

EUROPE

Austria - Wels
Tel: 43-7242-2244-39
Fax: 43-7242-2244-393

Denmark - Copenhagen
Tel: 45-4450-2828
Fax: 45-4485-2829

France - Paris
Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Munich
Tel: 49-89-627-144-0
Fax: 49-89-627-144-44

Italy - Milan
Tel: 39-0331-742611
Fax: 39-0331-466781

Netherlands - Drunen
Tel: 31-416-690399
Fax: 31-416-690340

Spain - Madrid
Tel: 34-91-708-08-90
Fax: 34-91-708-08-91

UK - Wokingham
Tel: 44-118-921-5869
Fax: 44-118-921-5820

10/05/07